## **BACKFLOW PREVENTION ASSEMBLY TEST REPORT**

WATER PURVE	Alderwood		ACCOUN	Г #
ASSEMBLY ID/FILE #/UTILITY DEVICE #			Meter #	
NAME OF PREMISE Tosti-Lane, Dave			Commercial 🗌 Residential 🔽	
SERVICE ADDRESS 3794 232nd PL SW			Briar	<u>ZIP</u> 98036
CONTACT PERSON Dave Tosti-Lane PHONE (425) 306-2773				06-2773
LOCATION OF ASSEMBLY On Street @ Meter				
DOWNSTREAM PROCESS Irrigation DCVA 🗹 RPBA 🗌 PVBA 🗌 OTHER				
NEW INSTALL □ EXISTING 🖌 REPLACEMENT □ REMOVED □ OLD SER.#				
APPROVED ASSEMBLY?YES $\checkmark$ NO $\Box$ PROPER INSTALLATION? YES $\checkmark$ NO $\Box$				
MAKE OF ASSE	MBLY <u>Febco</u>	MODEL <u>850</u>	SERIAL NO. <u>HF9</u>	<u>2665</u> SIZE <u>1"</u>
INITIAL	DCVA / RPBA		<u>RPBA</u>	PVBA / SVBA
TEST		CHECK VALVE NO.2	OPENED ATPSID	
PASSED 🔽	CLOSED TIGHT  ✓	CLOSED TIGHT	#1 CHECKPSID	OPENED AT PSID
FAILED	LEAKED            1.8         PSID	LEAKED            2.0         PSID	AIR GAP OK?	DID NOT OPEN
	CLEAN REPLACE PART	CLEAN REPLACE PART	CLEAN REPLACE PART	CHECK VALVE
NEW				HELD AT PSID
PARTS				
AND				CLEANED
REPAIRS				REPAIRED
TEST AFTER REPAIRS	CLOSED TIGHT	CLOSED TIGHT	RV EXERCISED	AIR INLET PSID
PASSED	LEAKED 🗌	LEAKED 🗌	OPENED AT PSID	
FAILED	PSID	PSID	#1 CHECK PSID	CHK VALVE PSID
AIR GAP INSPECTION: SUPPLY PIPE DIAMETER SEPARATION PASS _ FAIL _				
DETECTOR METER READING				
LEFT SERVICE AS FOUND Isolation valve: Open 🗌 Closed 🖌 SOV#1: Open 🗌 Closed 🖌 SOV#2: Open 🗌 Closed 🖌				
REMARKS:				
				CONFINED SPACE? No
			. NO. <u>B6074</u>	
			ERS PHONE # (425)830	
REPAIRED BY:				
FINAL TEST BY:		CERT	. NO	DATE
CALIBRATION DATE01-10-2024_GAUGE #05181290MODELMidwest 845_SERVICE RESTORED YES 🗔 NO 🔽				

A+ Backflow Inc (425) 830-3749